

Affected Parts



Positronic[®]

an Amphenol company

GLOBAL HEADQUARTERS

1325 N Eldon Ave
Springfield MO 65803 USA

USA | France | Singapore
+1 417 866 2322

info@connectpositronic.com

PCN-10660

Loctite Adhesive Change for Select Glued Components

Affected Part Number Schemas

ACCIS151104-*

ED***

FDA***

SK2957

****-2211

****-2735

****-S1065

****-S109

****-S1100

****-S1123

****-S1125

****-S1128

****-S1161

****-S1166

****-S1168

****-S1175

****-S1234

****-S1247

****-S1267

****-S1287

****-S1348

****-S1431

****-S1440

****-S1446

****-S1447

****-S1465

****-S1466

****-S1468

****-S1500

****-S1502

****-S1550

****-S1567

****-S1580

Affected Part Numbers

ACCIS151104-1

ACCIS151104-2

ACCIS151104-3

ACCIS151104-4

CBD24W7F85R7NT2X/AA-S1287

CBD3W3M93S00Z/AA-S1125

CBD3W3M93S00Z-S1125

CBD46W4F57R7NT20-S1175

CBD7W2F93S000/AA-14-S1468

CBM24W7M650000/AA-S1123

CBM24W7M650000-S1123

CBM24W7S65F000-S1123

CBM25W3M75R60V3S/AA-S1465

DD15M4R5NT20/AA-S1431

DD15M4R5NT20-S1431

DD26M4R400S/AA-S1267

DD44F40F00-S1348

DD44M40F00-S1348

DD44S40F00-S1348

DD62M40F00-S1348

DDB15FR7T2/15FR7T20-S1440

ED15F42S5000/AA-S455

ED37M420F0Z/AA-S684

ED37M420F0Z-S684

ED9F42R00X/AA-S549

ED9M420000/AA-S1600

ED9M42R300Z/AA-S1567

FDA9M330F0Z-S757

GAPL50M0T0LN/AA-S916

GFPL1M1FA0H/AA-15-2211

GFPL4M000H/AA-15-S109

HDC15M420000-S1065

HDC15M42B7000/AA-S1128

Affected Parts

****-S1587	HDC15M42R600Z-S1500
****-S1600	HDC15M50000-S1065
****-S1655	HDC15M50F00-S1161
****-S397	HDC15M5R30T2X-15-S1100
****-S399	HDC15M5R60T2X/AA-15-S1502
****-S455	HDC15M5R60T2X-15-S1502
****-S508	HDC15M5R80T5S/AA-50-S1465
****-S549	HDC15S5S5000/AA-S1655
****-S684	HDC25M320F00
****-S757	HDC25M42R300Z/AA-S1166
****-S802	HDC25M42R300Z-S1166
****-S916	HDC25M5R7000/AA-S1446
****-S929.1	HDC25M5R80T5S/AA-50-S1465
	HDC25S5R200X/AA-S1465
	HDC37M42R300Z/AA-S1166
	HDC37M42R300Z-S1166
	HDC37M5R7000/AA-S1446
	HDC50M420000/AA-14-S802
	HDC50M42R300Z-S1166
	HDC50M5R7000/AA-2735
	HDC50M5R7000/AA-S1446
	HDC50M5R700Z/AA-S1465
	HDC9M5R30T2X-15-S1100
	HDC9M5R600X/AA-S1447
	HDC9M5R60T2X/AA-15-S1502
	HDC9S42R5NT20/AA-S1431
	HDC9S42R5NT20-S1431
	HDC9S50000/AA-S929.1
	HDC9S5R200X/AA-S1465
	MDPC37MR2/37MR2Z-S1168
	MDX50M40200X/AA-S1587
	ODD15M4R600Z/AA-S1465
	ODD26M4R600Z/AA-S1465
	ODD26M4R700Z/AA-S1465
	ODD44S4R200X/AA-S1550
	ODD78M4000C-S1466
	ODD78M4R600Z/AA-S1465
	ODD78S4R200X/AA-S1465
	ODD78S4R200X/AA-S1550
	SGM14MSC00000-S508
	SGM14MSCT0000-S397
	SGM34MSC00000-S508
	SGM50MSC00000-S508
	SGM50SSCT0000/AA-S397
	SGM7MSCCESS0000-S508
	SGM7SSCESS0000-S508
	SMPL26M0NSS0LB/AA-S1234
	SMPL26M0T00-S399

Affected Parts

SMPL26S0NSS0LB/AA-S1580

SMPL26S0NSS0LB-S1580

SMPL4M0T0LB/AA-S1247